

Rodzaj uziemienia -taśmowo-prętowy

Linia SN 15 KV Instal. Proboszczewice zasilana z GPZ Przemysłowa				
LP.	Numer słupa	Wartość uziemienia do poprawy [Ω]	Wartość uziemienia po poprawie [Ω]	Uwagi
1	97/6A	30,04		
2	97/7A	15,21		
3	97/8A			urwane uziemienie
4	97/2A			urwane uziemienie
5	97/3A O1-1088	13,06		
6	97/4A O1-1089	21,33		
7	97/5A	12,41		
8	100	17,24		
9	98	12,14		
10	97/1A	22,1		
11	101	13,21		
12	114 (nowy nr 115)	21,43		
13	114/1 O1-1133	20,06		
14	119			urwane uziemienie
15	118			brak uziemienia
16	117 O1-1082	39,7		
17	123/3 O1-1350	147		uszkodzone uziemienie
18	122	741		uszkodzone uziemienie
19	121			brak uziemienia
20	124	12,03		
21	123/2	12,22		
22	125/2 S1-1081	284		urwane uziemienie
23	128	42,22		
24	127 O1-1080	83,01		
25	129/13	14,43		
26	129/15 O1-1449			brak uziemienia
27	129/9/1 O1-1079	27,04		
28	129/10 O1-1448	12,21		
29	129/2	12,24		
30	129/6			urwane uziemienie
31	131	12,41		
32	129			urwane uziemienie
33	135			urwane uziemienie
34	134			urwane uziemienie
35	133			urwane uziemienie
36	138/10			urwane uziemienie
37	138/11 O1-1076			urwane uziemienie
38	138/4			urwane uziemienie
39	138/5			urwane uziemienie
40	138/6			urwane uziemienie
41	164			urwane uziemienie
42	153	14,23		
43	O1-1073			uszkodzone uziemienie
44	23	53,12		
45	25	31,21		
46	41	25		urwana bednarka
47	37	14,5		