

Rodzaj uziemienia - taśmowo-prętowy

Linia SN 15 KV Nadułki 0024/30 zasilana z GPZ Staroźreby				
LP.	Numer słupa	Wartość uziemienia do poprawy [Ω]	Wartość uziemienia po poprawie [Ω]	Uwagi
1	127/31 (O5-1668)	17,22		
2	116/5 (O5-1658)	27,27		
3	119/1 (O5-1659)			brak uziemienia
4	127/1 (O5-1665)	18,35		
5	127/14 (O5-1667)	21,52		
6	108/15	24,25		
7	108/18	19,71		
8	108/1 (O5-1655)	18,51		
9	108/12 (O5-1656)	14,19		
10	80/112	22,63		
11	98/12			urwane uziemienie
12	98/13 (O5-1650)	19,74		
13	80/98 (O5-1634)	19,63		
14	80/108 (O5-1636)	18,33		
15	80/111 (O5-1635)	24,52		uszkodzone uziemienie
16	80/80 (O5-1633)	24,82		
17	80/81	18,57		
18	80/59 (O5-1631)	24,82		
19	80/63	13,44		
20	80/69			brak uziemienia
21	80/32			uszkodzona bednarka
22	80/48			uszkodzona bednarka
23	80/53			brak uziemienia
24	80/54			brak uziemienia
25	80/28 (O5-1638)	32,53		
26	80/43 (O5-1637)			uszkodzona bednarka
27	80/7 (O5-1647)	18,47		
28	80/24	20,52		
29	80/26	16,32		
30	74/20	24,62		
31	80/3	27,43		
32	74/7	29,53		
33	74/9	32,07		
34	74/19 (O5-1726)	13,52		
35	58	27,45		
36	74/1 (O5-1645)	12,53		
37	56/2 (O5-1643)	18,59		
38	9/22 (O5-1700)	28,62		
39	9,36 (O5-1701)	24,51		
40	9/45 (O5-1699)	32,44		
41	13			urwana bednarka