

## Rodzaj uziemienia -taśmowo-prętowy

Linia SN 15 KV Starożreby 0025/18 zasilana z GPZ Raciąż				
LP.	Numer słupa	Wartość uziemienia do poprawy [Ω]	Wartość uziemienia po poprawie [Ω]	Uwagi
1	81			urwana bednarka
2	108/55/3	27,1		
3	108/55/2	24,9		
4	108/49			brak uziemienia
5	108/25/9/4	14,1		
6	108/25/7	17,1		
7	108/17/7			urwana bednarka
8	O5-686			urwana bednarka
9	108/4/2			urwana bednarka
10	108	13,6		
11	O5-2545	18,3		
12	O5-1837	13,7		
13	O5-2544	14,9		
14	92	24,3		
15	88/75/3	12,5		
16	O5-2518	11,95		
17	88/65/34	13,6		
18	O5-2517	12,5		
19	88/65/26/16			wyorana bednarka (wyrwana)
20	88/65/26/8			urwana bednarka
21	O5-2846			urwana bednarka
22	88/65/9/6	14,2		wyrwana bednarka
23	O5-2470	12,5		wyorana bednarka
24	88/61/26	12,8		
25	88/61/10	21,1		
26	O5-2514	11,8		wyorana bednarka
27	O-752524	16,2		
28	88/29			brak uziemienia
29	63	9,8		wyorana i urwana bednarka
30	56	12,4		
31	54			urwana bednarka
32	47			wyrwana bednarka
33	O5-2537	18,5		
34	42/31	22,8		
35	O5-2539	25,1		
36	42/12/4			urwana bednarka
37	42/10	20,8		urwana bednarka
38	42/9	24,2		
39	42/8	21,4		
40	42/2			urwana bednarka
41	O5-2536			wyrwana bednarka
42	40	19,1		
43	O5-2535			wyrwana bednarka
44	24/7			urwana bednarka
45	24/5	17,7		
46	O5-2531	12,4		
47	18	16,3		
48	O5-2530	18,3		
49	AO5-2529	12,2		